


## Report Example: Basic EMP Study

Date: 7/31/2018  
 Gage: My Gage  
 Characteristic: Thickness  
 Operators (o): 3  
 Parts (p): 10  
 Trials (n): 3


Analyzed by: Bill  
 USL: 3  
 LSL: -3  
 Process Average:  
 Process Sigma: 2.5  
 Meas. Increment: 0.01

### Operator-Part Control Charts

**$\bar{X}$  Chart for Operator-Part Averages**



**R Chart for Operator-Part Ranges**



**Control Chart Calculations**

<u><math>\bar{X}</math> Chart</u>	$\bar{\bar{X}}$ 0.001	$LCL = \bar{\bar{X}} - A_2\bar{R}$ -0.348	$UCL = \bar{\bar{X}} + A_2\bar{R}$ 0.351
<u>R Chart</u>	$\bar{R}$ 0.342	$LCL = D_3\bar{R}$ -	$UCL = D_4\bar{R}$ 0.880

where  $A_2$ ,  $D_3$ , and  $D_4$  are control chart constants depending on subgroup size.

$A_2$ 1.023	$D_3$ -	$D_4$ 2.574
----------------	------------	----------------

**$\bar{X}$  Chart Analysis**

The  $\bar{X}$  chart shows the average value for each operator for each part.  
 The control limits on the  $\bar{X}$  chart are based on the average range.

The average range is representative of measurement error.  
 The  $\bar{X}$  chart control limits represent the variation obscured by measurement error.

- The relative utility of the measurement system increases:
- \* The more out of control points there are on the  $\bar{X}$  chart.
  - \* The further the out of control points are away from the control limits.

22 out of 30 points are out of control on the chart.

### R Chart Analysis


The R chart shows the results for the repeated measurements for each operator for each part. It is a check of the consistency of the measurement process between the operators.

*There is 1 out of control point on the R chart; the ranges are not consistent. The reason for the out of control point should be corrected and the study repeated.*


There are 54.7 degrees of freedom associated with the average range. It is recommended to have at least 10 degrees of freedom.

## ANOM Charts for Bias and Repeatability

### Main Effects (0.05 ANOME) Chart



### Mean Range (0.05 ANOMR) Chart



### ANOM Calculations

<u>Main Effects</u>	$\bar{X}$ 0.001	$LCL = \bar{X} - ANOME_{0.05}\bar{R}$ -0.070	$UCL = \bar{X} + ANOME_{0.05}\bar{R}$ 0.073
<u>Mean Range</u>	$\bar{R}$ 0.342	$LCL = LMR_{0.05}\bar{R}$ 0.234	$UCL = UMR_{0.05}\bar{R}$ 0.455

where ANOME, LMR, and UMR are scaling factors that depend on the amount of data.

ANOME <sub>0.05</sub>	LMR <sub>0.05</sub>	UMR <sub>0.05</sub>
0.209	0.685	1.331

### Main Effects Chart Analysis

This chart plots the average part values for each operator.  
 The purpose of the chart is to check for operator bias.  
 Points beyond the control limits are indications that bias exists.

*There is evidence of detectable bias between the operators.  
 Review the ANOME chart for the differences.*

### Mean Range Chart Analysis

This charts plot the average range values for each operator.  
 The purpose of the chart is to see if the test-retest error is the same for each operator.  
 Points beyond the control limits are indications that differences in repeatability exist.

*There is evidence of differences in the test-retest error between the operators.  
 Review the ANOMR chart for the differences.*

Repeatability (Test-Retest Error)	
$d_2$	$\sigma_{pe} = \bar{R}/d_2$
1.693	0.20181138

where  $d_2$  is a control chart constant depending on subgroup size.

Probable Error (PE) and Measurement Increment		
PE	0.136	Probable Error ( $0.675\sigma_{pe}$ )
0.2(PE)	0.0272	Smallest Effective Measurement Increment
2(PE)	0.272	Largest Effective Measurement Increment

PE is the minimum medium error of the measurement process.  
 50% of the measurements will fall within +/- one PE.  
 PE defines the effective resolution of the measurement process.  
 The resolution should be between 0.2(PE) and 2(PE).

*The measurement increment (0.01) is less than 0.2(PE),  
 increase the measurement increment so it is between 0.2PE and 2PE.*

Variance Components					
Component	Variance	% of Total	Estimates:		Sigma
Repeatability	0.0407	0.7%	$\sigma_{pe}^2$	Repeatability (pure error) variance	0.202
Reproducibility	0.0514	0.8%	$\sigma_o^2$	Reproducibility variance	0.227
R&R	0.0922	1.5%	$\sigma_e^2$	Combined R&R variance	0.304
Product	6.158	98.5%	$\sigma_p^2$	Product variance	2.481
Total	6.250		$\sigma_x^2$	Total variance	2.500

*Product variance estimated from the process sigma entered.*

$\sigma_o^2 = s_o^2 - (o/n \text{ o p})\sigma_{pe}^2$  where  $s_o^2$  = variance of operator averages.  
 $\sigma_p^2 = \sigma_x^2 - \sigma_e^2$

### Intraclass Correlation Coefficients

Intraclass Correlation Coefficient (Repeatability) = 0.9934  
 $\rho_{pe} = \sigma_p^2 / (\sigma_p^2 + \sigma_{pe}^2)$

Intraclass Correlation Coefficient (Repeatability & Reproducibility) = 0.9853  
 $\rho_e = \sigma_p^2 / (\sigma_p^2 + \sigma_e^2)$

### Type of Class Monitor

Based on Repeatability: This is a First Class Monitor

Based on Repeatability and Reproducibility: This is a First Class Monitor

ρ	Type of Monitor	Reduction of Process Signal <sup>a</sup>	Chance of Detecting ± 3 Std. Error Shifts <sup>b</sup>	Ability to Track Process Improvements <sup>c</sup>
0.8 to 1.0	First Class	Less than 10%	>99% with Rule 1	Up to Cp80 = 2.22
0.5 to 0.8	Second Class	From 10% to 30%	>88% with Rule 1	Up to Cp50 = 3.51
0.2 to 0.5	Third Class Monitor	From 30% to 55%	>91% with Rules 1, 2, 3, & 4	Up to Cp20 = 4.439
0.0 to 0.2	Fourth Class Monitor	Greater than 55%	Rapidly Vanishes	Unable to Track

Table reproduced with permission from EMP III Evaluating the Measurement System by Donald J. Wheeler, Copyright 2006 SPC Press.

<sup>a</sup>A signal occurring on a control chart is reduced in strength by 1 - square root of ρ<sub>o</sub>.

<sup>b</sup>The probability that the measurement process can detect a significant shift.

Rule 1: Point beyond the control limits.

Rule 2: 2 out of 3 consecutive points on the same side of the average are > 1 sigma from the average.

Rule 3: 4 out of 5 consecutive points on the same side of the average are > 2 sigma from the average.

Rule 4: 8 consecutive points on the same side of the average.

<sup>c</sup>The process capability where the measurement process will move down to a lower class.

### Watershed Specifications<sup>1</sup> and Precision to Tolerance Ratio

Watershed USL = 3.005  
 Watershed LSL = -3.005  
 Watershed Tol. = 6.01

% Mfg. Specs <sup>2</sup>	PE Used to Tighten Specs <sup>3</sup>	Mfg. LSL <sup>4</sup>	Mfg. USL <sup>4</sup>	Precision to Tolerance Ratio <sup>5</sup>	Precision + Bias to Tolerance Ratio <sup>6</sup>
85.0%	1	-2.86877732	2.86877732	4.53%	6.82%
96.0%	2	-2.73255464	2.73255464	9.07%	13.64%
99.0%	3	-2.59633196	2.59633196	13.60%	20.46%
99.9%	4	-2.46010927	2.46010927	18.13%	27.28%

<sup>1</sup>Watershed specification limits take into account the measurement increment.

Watershed USL = USL + 0.5(measurement increment)

Watershed LSL = LSL - 0.5(measurement increment)

Watershed Tolerance = Watershed USL - Watershed LSL

<sup>2</sup>% *Mfg Specs* is the probability that an item, with a measured value that falls between the Mfg. LSL and Mfg. USL, conforms to specifications.

<sup>3</sup>*PE Used to Tighten Specs* is the number of PE units used to reduce the watershed specifications.

<sup>4</sup>*Mfg. LSL* and *Mfg. USL* are the specifications based on the PE adjustments.

Example: 96%, Mfg. LSL = Watershed LSL + 2(PE) and Mfg. USL = Watershed USL - 2(PE)

<sup>5</sup>*Precision to Tolerance Ratio* is the % of the watershed tolerance consumed by the PE adjustment.

Example: For 96% Mfg. Specs,  $P/T = 4(PE)/\text{Watershed Tolerance}$

<sup>6</sup>*Precision + Bias to Tolerance Ratio* is the % of the watershed tolerance consumed by the PE adjustment using both the repeatability and reproducibility.